

# Crisis operations in an extreme environment



Jörgen Modin, inspector, Jämtland County Police



# Background

- On **15 March at 13:40 hrs**, the transport aircraft C-130 Hercules called "SIV" departed from Evenes, Norway, in order to carry out a flight to Kiruna, Sweden. The aircraft and its crew were part of the military exercise Cold Response, a Norwegian winter exercise with invited units from 14 nations.
- At **14.56 hrs**, the radar last had contact with the aircraft, when it was situated right to the west of the Kebnekaise massif. The aircraft was reported missing shortly after.
- Rescue operations were initiated, but because of the very rough weather in the area, the aircraft could not be found.
- On **16 March around 16:00 hrs**, a Norwegian P-3 Orion identified a number of orange coloured objects from a high altitude in the Kebnekaise massif. The crash site was thereafter determined.



# The site

- Sweden's highest point, 2,102 meters above sea level.
- two peaks, the south and the north peaks
- the crash site is located on the ridge between the two peaks
- free overflight approx. 100 meters up



**Polisen**

Jämtland County Police

# The aircraft

- C-130J Hercules,  
empty weight: 33,000 kg
- maximum take-off weight:  
approx. 79,000 kg
- cruising speed: 640 km/h
- approx. 8,000 kg of  
aviation fuel  
at the moment of the crash
- one of the world's  
most secure aircrafts!



**Polisen**

Jämtland County Police

# The crew

Captain Steinar Utne

Lieutenant Colonel Truls Audun  
Örpen

Captain Siw Robertsen

Captain Björn Yngvar Haug

Captain Ståle Garberg



**Polisen**

Jämtland County Police

# Images from Kebnekaise

Photo of the midnight sun, the ridge between the south and the north peaks.



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise

Way up  
to the south peak.



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise

The most common weather in the area.



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise

The base camp  
at Rabots glacier  
below the crash site.



**Polisen**

Jämtland County Police

# Images from Kebnekaise

Photo from  
below the crash site.



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise

Photo from  
above the base camp.



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise

Izor  
on the north peak.



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise

It is of great importance that the dog is secured to its handler in a professional way.



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise

Safety rope from the peak  
down to the search area.



**Polisen**


Jämtland County Police

19/02/2013

# Images from Kebnekaise

Izor's task was sometimes very difficult and demanding.

The search operations were often carried out on an almost vertical slope.



**Polisen**

Jämtland County Police

# Images from Kebnekaise

One difficulty that we had not encountered before was when Izor alerted to something on steep terrain.

At these moments, he had difficulty in holding on to the slopes.



# Images from Kebnekaise



# Images from Kebnekaise

An incredible number of distorted and sharp wreckage parts were found in the snow.



# Images from Kebnekaise

Resting time  
for a tired hero.



**Polisen**

Jämtland County Police

# Images from Kebnekaise



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise

The "usual"  
weather at the site.



**Polisen**

Jämtland County Police

# Images from Kebnekaise



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise



# Images from Kebnekaise

One of the many glacier crevasses in the search area.

This crevasse was more than seven meters deep.



**Polisen**

Jämtland County Police

# Images from Kebnekaise

Safety team



**Polisen**  
Jämtland County Police

19/02/2013

# Images from Kebnekaise

A dignified  
but difficult  
transport of  
found remains.




**Polisen**

Jämtland County Police

# Images from Kebnekaise

Identification of remains  
carried out in the field.



**Polisen**

Jämtland County Police

# Images from Kebnekaise




**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise




**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise




**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise



# Images from Kebnekaise



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise



**Polisen**

Jämtland County Police

19/02/2013

# Images from Kebnekaise



**Polisen**

Jämtland County Police

19/02/2013